



July 22, 2008

MR. FRANK DIERTL GENERAL MANAGER, ENGINEERING SERVICES MERCEDES-BENZ USA, LLC PO BOX 350 MONTVALE, NJ 07645-0350 NVS-215paw 08V-303

SUBJECT: INCORRECT SOFTWARE CALIBRATION NUMBER CODIFICATION

DEAR MR. DIERTL:

This letter serves to acknowledge Mercedes-Benz USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety defect in the products described below for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES BENZ/C CLASS/2005-2006, 2007-2008

MERCEDES BENZ/CL CLASS/2004

MERCEDES BENZ/CL CLASS/2008

MERCEDES BENZ/CLK CLASS/2003-2004, 2006-2008

MERCEDES BENZ/CLS CLASS/2008

MERCEDES BENZ/E CLASS/2003-2008

MERCEDES BENZ/G CLASS/2003

MERCEDES BENZ/M-CLASS/2006-2008

MERCEDES BENZ/R CLASS/2006 -2008

MERCEDES BENZ/S CLASS/2004, 2007-2008

MERCEDES BENZ/SL CLASS/2003-2004, 2006, 2009

MERCEDES BENZ/SLK CLASS/2005-2009

NHTSA Campaign Number: 08V-303

Mfg's Report Date: July 3, 2008

Components: ELECTRICAL

Potential Number of Units Affected: 404

Summary:

MERCEDES-BENZ IS RECALLING 404 MY 2006-2008 M-CLASS, R-CLASS, MY 2005-2009 SLK-CLASS, MY 2005-2008 C-CLASS, MY 2003-2004 AND 2006-2008 CLK-CLASS, MY 2003-2008 E-CLASS, MY 2004 AND 2008 CL-CLASS, MY 2008 CLS-CLASS, MY 2004 AND 2007-2008 S-CLASS, MY 2003 G-CLASS, AND MY 2003-2004, 2006 AND 2009 SL-CLASS VEHICLES. A SOFTWARE CALIBRATION NUMBER (SCN) CODING RECEIVED ON THE AFFECTED VEHICLES DURING A RECENT WORKSHOP VISIT WAS INCORRECT. DEPENDING ON THE MODEL YEAR AND MODEL AFFECTED, THE RESULTS OF AN INCORRECT SCN CODING CAN AFFECT A NUMBER OF VEHICLE SAFETY AND EMISSION FUNCTIONS INCLUDING THE FOLLOWING TYPES OF FUNCTIONS: (1) THE FUEL GAUGE READINGS MAY BE INCORRECT; (2) A STUCK FUEL-LEVEL SENSOR MAY NOT BE DISPLAYED IN THE INSTRUMENT CLUSTER; (3) THE OBD SYSTEM MAY CAUSE THE CHECK ENGINE LIGHT TO ILLUMINATE INCORRECTLY; AND, (4) THE SPEEDOMETER MAY BE OUT OF TOLERANCE.

Consequence:

IN THE EVENT OF A VEHICLE CRASH, THE ELECTRICAL FUEL PUMP MAY NOT RECEIVE A CRASH SIGNAL THAT IS REQUIRED FOR THE FUEL PUMP TO DISCONNECT AND PREVENT FUTURE FUEL DELIVERY AS DESIGNED.

Remedy:

DEALERS WILL RECODE THE SCN FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING AUGUST 2008. OWNERS MAY CONTACT MERCEDES-BENZ AT 1-800-367-6372.

Notes:

MERCEDES BENZ RECALL NO. 2008 070001. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at Patricia.wallace@dot.gov, Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

George H. Person

Chief, Recall Management Division

Office of Defects Investigation

Enforcement